

TABLE 2¹**Sludge Volumes Removed and Disposed of
by Location****Sludge Section
Livingston Rail Yard Remedial Investigation**

Location	Volume (cubic yards)
API separator pond	1192
Cinder pile lagoon	709
Overflow pond	3874
WWTP sump	932
In-line grit chamber	40
WWTP surge tank	10
WWTP grit chamber	32
WWTP grit chamber filter cake	80
Cinder pile sludge	5500
TOTAL	12,369

1 Most tables are from the BRA, RI and FSs and reformatted for the ROD. Envirocon, Inc. prepared tables in the RI and FSs. Camp Dresser & McKee prepared tables for the BRA.